

Version No.: 1 Issue Date: Nov 1, 2020

Voluntary product information based on the format of a safety data sheet

#### Section 1. IDENTIFICATION OF THE PRODUCT AND SUPPLIER

1.1 Product identifier

Trade name : Promax GP, Platinum 312, Platinum 309MoL, Platinum 316L,

Platinum NiFe, Promax 700, Platinum 943

1.2 Other means of identification

. \_

1.3 Recommended use of the chemical and restriction on use

Use : Electric arc welding

1.4 Details of principal suppliers (including name, address, phone number, etc.)

Supplier : Weldclass

Street address : 6 East West Place, Tamworth

NSW 2340, Australia

Telephone : +612 6764 9590

Email : sales@weldclass.com.au Website : www.weldclass.com.au

#### **Section 2. HAZARDS IDENTIFICATION**

2.1 Classification of the substance / mixture and any nation or regional information Classification according to Occupational Safety and Health (Classification, Labelling and Safety Data Sheet of Hazardous Chemicals) Regulations 2013

2.2 Label elements

Pictogram : Not applicable

Signal word : Not applicable Hazard Statement(s) : Not classified

Precautionary Statement(s) : P261 Avoid breathing fume/gas

P280 Wear protective gloves/protective clothing/eye protection/face

protection

P304 + P340 IF INHALED: Remove victim to fresh air and keep at rest in

a position comfortable for breathing

P337 + P313 If eye irritation persists: Get medical advice/attention

P233 + P403 Keep container tightly closed. Store in a well-ventilated place

2.3 Other hazards which do not result in classification or are not covered by the Regulations

During welding process: Overexposure to welding fumes can be dangerous

to health

Watch out for splatter, hot metal and slag. It may cause skin burn and cause

fire

Arc rays can injure eyes and burn skin. Electric shock can kill. Avoid

touching live electrical parts

E.&.O.E. Page 1 of 6



Voluntary product information based on the format of a safety data sheet

### Section 3. COMPOSITION AND INFORMATION OF THE INGREDIENTS OF THE HAZARDOUS CHEMICAL

#### 3.1 Substances

This product is a mixture and please refer to Section 3.2

#### 3.2 Mixtures

Chemical Name	CAS No.	Concentration Range				
		Promax GP	Platinum 312, 309MoL, 316L	Promax 700	Platinum 943	Platinum NiFe
Aluminium Oxide	1344-28-1	< 3%				
Calcium Carbonate	471-34-1	< 3%	1-5%		1-5%	
Carbon (C)	7440-44-0	< 5%	< 1%	< 10%		< 1%
Cellulose	9004-34-6	< 5%				
Chromium (Cr)	7440-47-3		< 30%	< 10%	< 30%	
Copper (Cu)	7440-50-8	< 5%	< 2%			< 1%
Iron (Fe)	7439-89-6	> 60%		> 60%	< 0.5%	>40%
Manganese (Mn)	7439-96-5	< 5%	< 3%	< 10%	< 2%	< 1%
Molybdenum (Mo)	7439-98-7		< 15%	< 10%		
Nickel (Ni)	7440-02-0		< 15%	< 10%		>50%
Phosphorus (P)		< 1%	< 1%	< 1%		< 1%
Potassium (K)	7440-09-7		< 0.04%	< 1%	< 1%	
Silicone (Si)	7440-21-3	< 1%	< 1%	< 10%	< 1%	< 1%
Silicone Dioxide	14808-60-7	< 5%				
Sulphur (S)	7704-34-9	< 1%	< 1%	< 10%		< 1%
Titanium Dioxide	13463-67-7	< 15%				

#### **Section 4. FIRST-AID MEASURES**

4.1 Description of first aid measures

Inhalation IF INHALED: If breathing is difficult, remove to fresh air and keep at rest

in a position comfortable for breathing. Call a physician if symptoms occur

Skin contact : IF SKIN BURN. Affected area to be treated by a doctor.

contact lenses, if present and easy to do. Continue rinsing.

Ingestion: IF SWALLOWED. Call a physician.

4.2 Most important symptoms and effects, acute and delayed

Inhalation: Inhalation of vapour may cause irritation of the respiratory system in

susceptible persons.

4.3 Indication of any immediate medical attention and special treatment needed, if necessary

: Not applicable

### **Section 5. FIRE-FIGHTING MEASURES**

5.1 Extinguishing media

Suitable extinguishing : Carbon dioxide (CO2), powder or diffuse jet of water.

media In case of major fire: Extinguish fire with diffuse jet of water or foam

5.2 Specific hazards arising from the chemical

: Not applicable

5.3 Special protective equipment and precautions for fire-fighters

: Wear self contained breathing apparatus

E.&.O.E. Page 2 of 6



Voluntary product information based on the format of a safety data sheet

#### Section 6. ACCIDENTAL RELEASE MEASURES

6.1 Personal precautions, protective equipment and emergency procedures

: Mechanical ventilation and local exhaust ventilation must be adequate to keep fume concentrations within safe limits. Use respiratory equipment when welding in a confined space. Wear eye and skin protection plus protective clothing appropriate to welding.

6.2 Environmental precautions

: Try to prevent the material from entering drains or water courses

6.3 Methods and material for containment and cleaning

: Sweep up the floor

#### **Section 7. HANDLING AND STORAGE**

7.1 Precautions for safe handling

Preventive handling : Ensure adequate ventilation for the welder and others. Use respiratory

precautions equipment when welding in a confined space. Wear eye and skin protection

plus protective clothing appropriate to welding. Remove all flammable

materials and liquids before welding

General hygiene : Wash hands before breaks.

7.2 Conditions for safe storage, including any incompatibilities

: Store welding consumables inside a room without humidity. Do not store welding consumables directly on the ground. Store away from chemical

substances like acids which could cause chemical reactions.

#### Section 8. EXPOSURE CONTROLS AND PERSONAL PROTECTION

8.1 Control parameters

Welding Fumes (NOC) : PEL - 8hr TWA =  $5 \text{ mg/m}^3$ 

8.2 Appropriate engineering controls

: Mechanical ventilation and local exhaust ventilation must be adequate to

keep fume concentrations within safe limits

8.3 Individual protection measures, such as personal protective equipment

Eye / face protection : Wear welding shield Skin protection : Wear welding glove

Respiratory protection : Use respiratory equipment when welding in a confined space, for example

N95 Dust Mask or half face respirator with filter

#### Section 9. PHYSICAL AND CHEMICAL PROPERTIES

9.1 Information on basic physical and chemical properties

Appearance : Rod, Grey

Form : Metal wire with flux coating

Odour : Odourless

Odour threshold : Not applicable

pH: Not applicable

Melting point / Freezing point : > 1500 °C

Initial boiling point and boiling range : Not applicable

Flash point : Not applicable

Evaporation rate : Not applicable

Flammability (solid gas) : Not applicable

Upper / lower flammability or : Not applicable

explosive limits

E.&.O.E. Page 3 of 6



Voluntary product information based on the format of a safety data sheet

Vapour pressure : Not applicable
Vapour density : Not applicable
Relative density : Not applicable
Solubility(ies) : Immisible

Partition coefficient: n-octanol / water : Not applicable

Auto-ignition temperature : Not applicable Decomposition temperature : Not applicable

Viscosity : Not applicable Specific Gravity : > 5 g/cm<sup>3</sup>

#### Section 10. STABILITY AND REACTIVITY

10.1 Reactivity

: Not applicable

10.2 Chemical stability

Stable at normal conditions.

10.3 Possibility of hazardous reactions

: Not applicable

10.4 Conditions to avoid

: None under normal conditions

10.5 Incompatible materials

: Not applicable

10.6 Hazardous decomposition products

: Welding fumes and gases

### **Section 11. TOXICOLOGICAL INFORMATION**

#### 11.1 Information on toxicological effects

Conditions to avoid: none in the form supplied

Overexposure to welding fumes can be dangerous to health, can cause dizziness, nausea and irritation to nose, throat or eyes

Acute Toxicity : Not classified

Skin Corrosion / Irritation : Not classified

Serious Eye Damage or Eye

Irritation

: Not classified

Respiratory Sensitization : Not classified

Skin Sentization : Not classified

Germ Cell Mutagenicity : Not classified

Carcinogenicity : Not classified

Reproductive Toxicity : Not classified

Specific Target Organ Toxicity : Not classified

- Single Exposure

E.&.O.E. Page 4 of 6



Voluntary product information based on the format of a safety data sheet

Specific Target Organ Toxicity

- Repeated Exposure

: Overexposure to welding fumes can be dangerous to health, can cause

dizziness, nausea and irritation to nose, throat or eyes

Aspiration Hazard : Not classified

#### **Section 12. ECOLOGICAL INFORMATION**

12.1 Ecotoxicity

: The welding process can effect the environment if welding fume is released directly into the atmosphere. Residues from welding consumables could degrade and accumulate into soils and ground water.

12.2 Persistence and degradability

: Not applicable

12.3 Bio accumulative potential

: Not applicable

12.4 Mobility in Soil

: Not applicable

12.5 Other adverse effects

: Not applicable

#### **Section 13. DISPOSAL INFORMATION**

Disposal Information : Dispose of any product, residue, filter or packing material according to

national and local regulations.

### Section 14. TRANSPORTATION INFORMATION

14.1 UN number

Not applicable

14.2 UN proper shipping name

Not applicable

14.3 Transport hazard class (es)

Not applicable

14.4 Packing group, if applicable

Not applicable

14.5 Environmental hazards

: Not applicable

14.6 Transport in bulk (according to Annex II of MARPOL 73/78 and the IBC Code)

: Not applicable

14.7 Special precautions

: Not applicable

#### **Section 15. REGULATORY INFORMATION**

15.1 Safety, health and environmental regulations / legislation specific for the substance or mixture.

: Classification according to Occupational Safety and Health (Classification, Labelling and Safety Data Sheet of Hazardous Chemicals) Regulations 2013

E.&.O.E. Page 5 of 6



Voluntary product information based on the format of a safety data sheet

#### Section 16. OTHER INFORMATION

16.1 Key / legend to the abbreviations and acronyms used in the SDS

SDS: Safety Data Sheet

PEL: Permissible Exposure Limit TWA: Time Weighted Average

16.2 Other information deems necessary by a supplier

: The information contained in the Safety Data Sheet is based on our data available on the date of publication. The information is intended to aid the user in controlling the handling risks; it is not to be construed as a warranty or specification of the product quality.

The user is responsible for ensuring that appropriate precautions are taken and for satisfying themselves that the data are suitable and sufficient for the product's intended purpose. In case of any unclarity we advise consulting the supplier or an expert.

E.&.O.E. Page 6 of 6